

School Facility Conditions and Planned Improvements

The District provides a safe and clean environment for learning and growing. All sites have adequate classroom space, office facilities, libraries, and computer labs that support the instructional program. All sites have emergency plans in place with procedures for staff and students in case of fire, earthquakes, and other disasters. Emergency drills are held routinely. Staff members supervise all playgrounds during school hours. In order to ensure a safe environment at all sites, district security personnel monitor campuses on a daily basis. Maintenance is an on-going process provided by the district maintenance and operational department. All staff members have identification badges.

Year and month of the most recent FIT report

4/1/2021

System Inspected	Rate Good	Rate Fair	Rate Poor	Repair Needed and Action Taken or Planned
Systems: Gas Leaks, Mechanical/HVAC, Sewer	X			
Interior: Interior Surfaces		X		1: loose ceiling tiles / very dirty 12: ceiling tiles / dirty 125: ceiling tiles missing 133 principal: plaster flaking 140: holes in drywall 143: ceiling tile damage 19: small wall damage 20: ceiling tile damage 41: missing ceiling tiles 41a girls: peeling paint 41d: floor failing 42: missing ceiling tiles 44: missing ceiling tiles 45: missing ceiling tiles 46: missing ceiling tiles 47: missing ceiling tiles 48: missing ceiling tiles 49 storage: wall damage 51: ceiling tile damage 54: missing ceiling tiles 58: missing ceiling tiles 60a boys: floor worn 61a: floor failing / dirty 61b: floor worn 61d girls: floor worn / dirty / graffitti 70: carpet worn 74: wall damage 81c girls: floor worn / very dirty / graffitti 81f: floor failing 82b boys: dirty / graffitti 91: floor dirty / floor tile damage boys: wall damage / graffitti / dirty g2 pe office: ceiling tiles missing g4 boys locker: ceiling damage / dirty girls: graffitti / dirty

School Facility Conditions and Planned Improvements

<p>Cleanliness: Overall Cleanliness, Pest/Vermin Infestation</p>		X	<p>1: loose ceiling tiles / very dirty 10: dirty 100 electrical: dirty 105: dirty 106: dirty 109a: dirty 109b: dirty 109d electrical: storage clutter / panel blocked / dirty 10b electrical: dirty 12: ceiling tiles / dirty 121 vestibule: clutter 122 makeup: exterior trash 122: dirty 124: dirty 125: dirty 126: dirty 127: dirty 128: dirty 130: combustible storage / very dirty 132: very dirty 152: floor dirty 17: floor unswept 32: office cluttered 44: missing ceiling tiles 50: dirty 50b storage: dirty 52: ü 60 storage: dirty 61a: floor failing / dirty 61c custodian: dirty 61d girls: floor worn / dirty / graffitti 62: dirty 63: dirty 65: dirty 69: very dirty 76: floor dirty 81c girls: floor worn / very dirty / graffitti 81d custodian: very dirty 81e: dirty 82b boys: dirty / graffitti 85: floor dirty 91: floor dirty / floor tile damage 92: dirty 94: dirty</p>
---	--	---	--

School Facility Conditions and Planned Improvements

			<p>95a: clutter / dirty 97: dirty 98a: dirty 98b: office very dirty / clutter 98g storage: dirty 99: floor tile damage a3: dirty a4: dirty boys: wall damage / graffiti / dirty custodian109c: dirty g1 pe office: dirty g10 girls: dirty g12 custodian: dirty g12a electrical: dirty g4 boys locker: ceiling damage / dirty g6: dirty g8 boys: dirty / graffiti g9 electrical: dirty girls: graffiti / dirty team locker: very dirty workshop: poor housekeeping</p>
Electrical	X		
Restrooms/Fountains: Restrooms, Sinks/ Fountains	X		<p>Room 62: Drinking fountain/hydration station on-operational Room 68: Drinking fountain non-operational</p>
Safety: Fire Safety, Hazardous Materials	X		<p>109d electrical: storage clutter / panel blocked / dirty 130: combustible storage / very dirty 137: clutter storage / panel blocked 16: excess paper 24: ext. cords 30: panel blocked 34: panel blocked 93: ext.cord</p>
Structural: Structural Damage, Roofs	X		61: ü
External: Playground/School Grounds, Windows/ Doors/Gates/Fences	X		122 makeup: exterior trash

Overall Facility Rate

Exemplary	Good	Fair	Poor
	X		